30 Year Reserve Study for North Shore Terrace Condominium, Newport OR By Ted DeBit, owner Spy Glass Homes

VISUAL INSPECTIONS

A visual inspection was made of six building containing 32 units for North Shore Terrace Condominiums. This inspection included the exterior of the structures, the doors, windows, garage doors, siding, fencing, decks front and rear, roofing, skylights, painting, asphalt, gutters / down spouts, sewer pump and retaining wall. The urgent repair, maintenance and reserve budgets are based on the time in service of the buildings and the repairs that already have been provided to each building. I have estimated the life of the different components for each building and provided a budget based on the expected useable life of the components.

BUILDING OBSERVATIONS

Building # 66

This building was put in service in 1992 that puts the aging of the building at 17 years. The urgent repair required for this building is the asphalt streets and parking, east garage door and rear decks. The entry doors, sliding doors, windows, front decks, gutters / downspouts and painting are in the maintenance budget. The fencing for this unit is in need of repair, I put this item in the reserve budget, projected over 10 years so that after collecting the allotment for one year the repairs could begin. This saves it from being added to the urgent repair budget. The concrete composite siding for this building should last the actual life of the building if the painting maintenance schedule is followed. The reserve budget includes the garage doors, fencing, roofing and skylights, painting and asphalt. The asphalt is in both budgets because the repair and sealing needs to be done immediately in order preserve the viability of the asphalt, if not addressed the system will fail with a tremendous cost to the budget. The balance for the reserve budget is for sealing the asphalt every ten years for 30 years and then having an overlay done to give a new 30 life to the system. The reserve budget is projected over a 30 year period with a 3% inflation rate included. The budgets should be reviewed every 5 to 7 years to keep them in line with current market conditions.

Building #76

This building was put in service in 1993 that puts the aging of the building at 16 years. This building has the same conditions as building # 66, except for the urgent repair budget and the reserve budget. The garage doors are in the reserve budget in this building and the roofing reserve is projected over 8 years instead of 30 years due to the expected life of the system.

Building #85

This building was put in service in 1998 that puts the aging of the building at 11 years. This building has the same conditions as the prior buildings except for the urgent repair budget and the reserve budget. The urgent repair budget contains the rear and entry decks. The reserve budget for the roof is projected over 12 years instead of 30 years due to the life of the system.

Page 1 of 4 6/2/2009

30 Year Reserve Study for North Shore Terrace Condominium, Newport OR By Ted DeBit, owner Spy Glass Homes

Building #86

This building was put in service in 1992 that puts the aging of the building at 17 years. This building has the same conditions as the prior buildings except for the urgent repair budget. The siding of this building is composed of concrete composite siding on the west and south sides of the building and L P siding on the north and east sides of the structure. The LP siding has failed with a 20% plus moisture content. This component should be addressed after the asphalt sealing and repair project is completed.

Building # 96 A-D

This building was put in service in 1994 that puts the aging of the building at 15 years. This building has the same conditions as the prior buildings except for the urgent repair budget and a separate fund for the sewer extractor pump and the reserve budget for the roof. The roof is projected at a 10 year expected life. The urgent repair budget is for the Weyerhaeuser siding that has failed on the east and north and south side of the building with a moisture content of 20 % plus. This repair should be completed after the repair to the siding on building # 86. The west side and 75% of the south side of the building is composed of concrete composite siding that is in good repair, this siding will last the life of the building if the painting maintenance schedule is followed.

Building #96 E-H

This building was put in service in 1996 that puts the aging of the building at 13 years. This building has the same conditions as the prior buildings except for a separate budget for the sewer extractor pump. The siding is a concrete composite that will last the life of the building if the painting maintenance schedule is followed. The roof was projected over a 10 year span for the reserve budget.

Page 2 of 4 6/2/2009

BUDGETS

COMPONETS

FRONT DOORS: #32, MAINTEANCE \$2400.00 / YR. \$6.25 / MO. / UNIT WINDOWS: 2,900 Sq ft MAINTENACE \$3330.00 / YR. \$8.67 / MO. / UNIT S/L DOORS: 1950 Sq ft MAINTENANCE \$1962.00 / YR. \$5.11 / MO. / UNIT GARAGE DOORS: 2940 Sq ft RESERVE \$23,150.00 30 YRS \$4.88 / MO. / UNIT GARAGE DOORS: 62 Sq ft URGENT REPAIR \$557.00 SEE NARRITAVE #66

SIDING: URGENT REPAIR \$ 86,000.00 SEE NARRITIVE

SIDING: TOTAL Sq ft 57,570

FENCING: 1,395 Lf. PROJECTED 10 YRS. \$51,275.00 \$18.01 / MO. / UNIT FENCING: SEE NARRITIVE \$10.80 / MO. / UNIT AFTER REPLACEMENT

ENTRY DECK: MAINTENANCE \$640.00 /YR \$1.67 / MO. / UNIT ENTRY DECK: URGENT REPAIR \$15,853 SEE NARRITIVE

ENTRY DECK: TOTAL Sq ft. 640

REAR DECK: MAINTENANCE \$4,255 /YR \$11.08 /MO. / UNIT

REAR DECK: URGENT REPAIR \$50,528

REAR DECK: Sq ft 4,255

ROOFING: SEE NARRITIVE FOR PROJECTINS \$69.75 / MO. / UNIT

ROOFING: TOTAL PROJECTED / BLD. AT DIFFERENT LIFES LEFT \$231,500.00

ROOFING: TOTAL Sq ft 54,000

SKYLITES: PROJECTED 30 YRS \$69,371.00 \$6.02 / MO. / UNIT

SKYLITES: Sq ft 1,720

PAINTING: PROJECTED FOR 5 YRS. \$18,316.00 \$9.54 / MO. / UNIT

PAINTING: Sq ft 57,570

ASPHALT: URGENT REPAIR \$7,554.00 SEE NARRITIVE

ASPHALT: 20 YR PROJECTED SEAL COAT \$3.55 / MO. / UNIT

ASPHALT: 30 YR PROJECTED FOR OVERLAY \$12.41 / MO. / UNIT

ASPHALT: SEE NARRITIVE

ASPHALT: Sq ft 39,000

GUTTERS, DOWN SPOUTS: MAINTENANCE \$1,655.00 / YR \$4.31 / MO. / UNIT

GUTTERS, DOWN SPOUTS: Lf 5,350

RETAINING WALL: 30 YRS PROJECTED \$8640.00 / \$.75 /MO. / UNIT

Page 3 of 4 6/2/2009

30 Year Reserve Study for North Shore Terrace Condominium, Newport OR By Ted DeBit, owner Spy Glass Homes

URGENT REPAIR BUDGET

Totals

ASPHALT SEALING AND REPAIR \$ 7,554.00

SIDING REPAIR \$86,000.00

REAR DECKS \$ 50,528.00

ENTRY DECK \$ 15,853.00

GARAGE DOOR \$ 557.00

TOTAL \$ 160,492.00

SEWER PUMP (FOR BLDS. # 96) \$ 2,000.00

SEWER PUMP MAINTENANCE

PER UNIT PER MONTH FOR BLDS # 96 \$ 3.00

MAINTENANCE BUDGET

PER UNIT PER MONTH \$ 37.09

RESERVE BUDGET

PER UNIT PER MONTH \$ 124.91

Page 4 of 4 6/2/2009